STERIS<sup>®</sup> VERIFY<sup>™</sup> STEAM Integrating Indicator Safety Data Sheet

Version: 1.0

## 1. Identification of the Substance and Company VERIFY<sup>™</sup> STEAM Integrating Indicator Product No. Reference table below SDS No. S295US

NFPA 704 HAZARD RATING: HEALTH: 0 FIRE: 0 REACTIVITY:

0

asksteris\_msds@steris.com

## Date Created: 06/21/2015 Date Revised: 1/17/2023 Date Reviewed: N/A

STERIS Corporation, P.O. Box 147, St. Louis, Mo 63166, US Emergency Telephone No. 1-314-535-1395 (STERIS); 1-800-424-9300 (CHEMTREC) Telephone Number for information: 1-800-548-4873 (Customer Service – Healthcare Products)

PRODUCT NAME:	PRODUCT NUMBER:
VERIFY <sup>™</sup> STEAM Integrating Indicator 4" x ¾" (250 strips/pk)	PCC064
VERIFY <sup>™</sup> STEAM Integrating Indicator 4" x ¾" (8 pks/box; 250 strips/pk)	PCC064B
VERIFY <sup>™</sup> STEAM Integrating Indicator 4" x ¾" (1,000 strips/pk)	PCC065
VERIFY <sup>™</sup> STEAM Integrating Indicator 4" x <sup>3</sup> ⁄ <sub>4</sub> " (2 pks/bx: 1,000) strips/pk)	PCC065B
VERIFY <sup>™</sup> STEAM Integrating Indicator 4" x <sup>3</sup> ⁄ <sub>4</sub> " (200 strips/pk)	PCC066
VERIFY <sup>™</sup> STEAM Integrating Indicator 5CM 2" X ¾" (500 strips/pk)	PCC067
VERIFY <sup>™</sup> STEAM Integrating Indicator 5CM 2" X <sup>3</sup> ⁄ <sub>4</sub> " (4 pks/cs; 500 strips/pk)	PCC067B
SHIPPING INFORMATION:	NOT RESTRICTED

These products are NOT hazardous products according to the OSHA Hazard Communication Standard, 29 CFR 1910.1200.

VERIFY<sup>™</sup> STEAM Integrating Indicators are manufactured in the absence of latex and dry natural rubber.

VERIFY<sup>™</sup> STEAM Integrating Indicators are manufactured in the absence of lead and other heavy metals.

The information on this sheet is not a specification and does not guarantee specific properties. The information is intended to provide general knowledge as to health and safety based upon our knowledge of the handling, storage and use of the product. It is not applicable to unusual or non-standard uses of the product or where instruction or recommendations are not followed.